



TOOL#	ØA +.000 002	B +.010 010	PIN TYPE	QTY.		MATERIA	ıL.
KSTCAS10	.622	.656	II	2	1018	RND. BAR	Ø3/4 x 3/4
KSTCAS12	.747	.656	III	2	1018	RND. BAR	Ø3/4 x 3/4

NOTES

1. BREAK ALL SHARP CORNERS (.015/.03).


RED RED	BARN	1 MA	CHIN	E	
	CAS##				
SWAGING	TDDL;	LOCA.	TING Pi	IN	
DWG NO.	(see	char	^t)-15	REV 1	
UNLESS OTHERWISE DIMENSIONS ARE I		DRAWN BY:	PERRIT	Т	
TOLERANCES ON:	IV II VOI ILO	APPROVED			
.XXX ± .005 FRACT	IONS ± 1/32	HEAT TREAT			
	GLES ±.5°	FINISH SPEC	BLACK D	XIDE	
UNLESS OTHERWISE S	SPECIFIED	US	SED ON BEARING	3	
1. BREAK ALL SHARE		SEE Pg. 1			
.015 x 45° PR .015 2. DIMENSIONAL LIMITS APPLY					
SCALE NTS	DATE 8-1	3-08	SHEET 9	of 9	





NOTES 1. BREAK ALL SHARP CORNERS (.015/.03).


® RED BARN	N MACHINE						
TITLE KSTCAS##							
SWAGING TOOL; SECONDARY SEAT							
DWG NO. TOOL# (See	chart)-13 REV 1						
UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES TOLERANCES ON:	DRAWN BY: PERRITT APPROVED						
DECIMALS .XXX ± .005 .XXX ± .005 .XX + .01 .X + .1 ANGLES ± .5°	HEAT TREAT FINISH BLACK DXIDE						
UNLESS OTHERWISE SPECIFIED	USED ON BEARING						
1. BREAK ALL SHARP EDGES .015 x 45° PR .015 R	SEE Pg. 1						
2. DIMENSIONAL LIMITS APPLY AFTER PLATING							
SCALE NTS DATE 8-1	3-08 SHEET 8 of 9						



TOOL#	ØA +.000 020	ØB +.005 005	ØC +.002 002	D +.002 002		MATERIA	L
KSTCAS10	2.125	1.687	0	0	4140 Q&T	RND. BAR	Ø2-1/8 x 1-1/8
KSTCAS12	2.125	1.687	0	0	4140 Q&T	RND. BAR	Ø2-1/8 x 1-1/8
							·

<u>NOTES</u>
1. BREAK ALL SHARP CORNERS (.015/.03).


1	RED	BARI	1 M	ACH	INE		
TITLE	KS7 SWAGING	CAS## TOOL;			SEAT		
DWG NO.	TOOL#	‡ (see	cha	rt)-	-11	REV 1	
TOLERAN			DRAWN BY: PERRITT APPROVED				
DECIMA .XXX ± .XX ‡	.005 FRACT	IONS ± 1/32 GLES ±.5°	HEAT TREAT FINISH SPEC	BLA	СК ПХІЛ	E	
UNL	ESS OTHERWISE		USED ON BEARING				
	BREAK ALL SHARF .015 x 45° PR .015	5 R	SEE Pg. 1				
	NSIONAL LIMITS APPLY.			louer-			
SCALE	STN	DATE 8-1	3-08	SHEET	7 of	` 9	



TOOL#	ØA +.000 001	ØB +.005 005	C +.010 010	D +.020 020	MATERIAL
KSTCAS10	.129	.188	.104	1.000	MCMASTER-CARR PN: 98378A909
KSTCAS12	.129	.188	.104	1.000	MCMASTER-CARR PN: 98378A909

<u>NOTES</u>
1. BREAK ALL SHARP CORNERS (.015/.03).


	RB F	RED	Br	ARN		МА	CH	IN	Ε	
TITLE				S##_						
		2 M F	リコン	NG T	ШL	ز ــالـ	PIN			
DWG NO.	Т	·00L#	± (-hai	ν+)-	<u> </u>		REV 1
	ļ		т 🔨	⊃ C C	_	_	\ \ /	/	- 1	1
UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES						WN BY:	PE	RRI	ΤΤ	
TOLERA	ANCES ON		• 11 • 01 12	_0	APPROVED					
DECIN .XXX ±		FRACTI	ONS +	1/32	HEA TRE	AT				
	.01		GLES ±.		FIN	ISH C	BLAC	K 🛭	XIDE	
.,,	• • • • • • • • • • • • • • • • • • • •	HERWISE S	PECIFI	FD	USED ON BEARING					
UNLESS OTHERWISE SPECIFIED 1. BREAK ALL SHARP EDGES .015 x 45° PR .015 R						SEE Pg. 1				
2. DII		45° PR .015 IMITS APPLY A		ATING						
SCALE	NT	S	DATE	8-13	3-	08	SHEET	6	of	9




TOOL#	ØA +.001 001	ØB +.000 002	C +.000 010	MATERIAL		
KSTCAS10	.131	.622	.375	BRONZE RND. BAR	Ø3/4 x 1/2	
KSTCAS12	.131	.747	.375	BRONZE RND. BAR	Ø3/4 x 1/2	
	I	I	l			

<u>NOTES</u>
1. BREAK ALL SHARP CORNERS (.015/.03).


	® RED	BA	<u> 181</u>	I Mr	4CH	INE		
TITLE	KST SWAC			SEF L; (_		
DWG NO	T:00Li	‡ (<u>·</u>	566	·cho	urt)-	-7	REV 1	
TOLER	INLESS OTHERWISE DIMENSIONS ARE II ANCES ON:		DRAWN BY		RRITT		7	
DECIN .XXX ± .XX	.005 FRACTI	ONS ± 1. GLES ±.5		HEAT TREAT FINISH SPEC				_
	NLESS OTHERWISE S	SPECIFIE	D	USED ON BEARING				
	1. BREAK ALL SHARF		SEE Pg. 1					
2. DII	015 x 45° PR .015 x 45° PR.						٦	
SCALE	NTS	DATE	8-13	3-08	SHEET	5 of	f 9	٦







TOOL#	TYPE	+.001 001	ØB +.001 001	(R) C +.002 002	D +.001 001	+.005 000	ØF +.000 005	MATERIAL			
KSTCAS10	I	.335	.310	.500	0	0	0	.310 MINUS	GAGE PIN	MSC#89031009	
KSTCAS12	I	.335	.310	.500	0	0	0				

® RED	BARN	I MA	CHI	ΝE				
	TCAS##							
SWAGING TOOL; ROLLER (QTY. 3)								
DWG NO. T	‡ (see	· chai	rt)-5	5	REV 1			
UNLESS OTHERWISE DIMENSIONS ARE II		DRAWN BY:	PERR	RITT				
TOLERANCES ON: DECIMALS	VIIVOLIES	APPROVED						
VVV 1 00F	ONS ± 1/32	HEAT TREAT						
	GLES ±.5°	FINISH SPEC						
UNLESS OTHERWISE S	SPECIFIED	USED ON BEARING						
1. BREAK ALL SHARF		SEE Pg. 1						
.015 x 45° PR .015 2. DIMENSIONAL LIMITS APPLY								
SCALE NTS	DATE 8-10	3-08	SHEET 4	of	9			





	REVISIONS			
REV	DESCRIPTION	DATE	INITIAL	APPROVED
1	-1 CH'D TOL. (H) WAS +/002 IS +/005.	6/17/13	ВІМ	GE



BEARINGS (COVE	
BEARING #	TOOL#
CAS10-31A1-518	KSTCAS10
S251W125-5, CAS12-31A1-518	KSTCAS12
_	

NOTES

- 1. -5 ROLLERS MUST TURN FREELY IN -3 RETAINER POCKETS.
- 2. -5 ROLLERS & -3 RETAINER MUST TURN FREELY WHEN TOOL IS COMPLETELY ASSEMBLED.
- 3. FLAT END OF ROLLERS MUST FACE TOWARDS THE CENTER OF THE TOOL WHEN ASSEMBLED.

ASSY QTY	В/О	PART#	UNIT	DESCRIPTION	B/O INFORMATION OR SPECIFICATIONS	Pg.	TITLE
		-1	1	ROLLER FIXTURE	SEE CHART	2	DWG NO.
		-3	1	RETAINER	SEE CHART	3	J DWG NO.
		-5	3	ROLLER	SEE CHART	4	U
		-7	1	GUIDE	SEE CHART	5	TOLERA
		-9	1	PIN	SEE CHART	6	.xxx ±
		-11	1	PRIMARY SEAT	SEE CHART	7	.xx ±
		-13	0 or 1	SECONDARY SEAT	SEE CHART	8	UN 1
		-15	1 or 2	LOCATING PIN	SEE CHART	9	2, DIM
	B/O	-17	1	SOCKET HEAD SET SCREW	#8-32 x 1/4	N/S	SCALE

® RED BARN MACHINE

KSTCAS## SERIES TRI-ROLLER SWAGING TOOLS

DWG NO. REV CHART ABOVE) UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES DRAWN BY: PERRITT APPROVED TOLERANCES ON: DECIMALS LISTED PER ITEM .XXX ± .005 .XX ± .01 .X ± .1 FRACTIONS ± 1/32 LISTED PER ITEM ANGLES ±.5° USED ON BEARING UNLESS OTHERWISE SPECIFIED 1. BREAK ALL SHARP EDGES SEE ABOVE .015 x 45° PR .015 R 2. DIMENSIONAL LIMITS APPLY AFTER PLATING

8-13-08 SHEET

1 of 9

DATE

NTS

		REVISIONS									
[REV	DESCRIPTION	DATE	INITIAL	APPR						
	_		-	-	_						

						1,			V)		® RED BARN MACHINE	
ASS QT	Y ASS Y QTY	Y B/C	PART#	UNIT		DESCRIPTION				MAT.	B/O INFORMATION OR SPECIFICATIONS	Pg.	TITLE ——	
			-1	1	RND			X		6061	Ø8-1/4 x 3-7/8	2	DWG NO	RE
						\mathcal{L}	$oldsymbol{\mathcal{X}}$						UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES TOLERANCES ON: DECIMAL PROVED DECIMAL PROVED	_
							\ '						DECIMALS .XXX ± .005 .XX ± .01 .X ± .01 .X + .00 OT IF DIVISION DECISION USED ON MODEL	
						<u> </u>							UNLESS OF HERWISE SPECIFIED 1. BREAK ALL SHARP EDGES .015 x 45° PR.015 R 2. DIMENSIONAL LIMITS APPLY AFTER PLATING	_
Г	ASS	Y											$^{\text{SCALE}}$ NTS $^{\text{DATE}}$ 8–15–07 $^{\text{SHEET}}$ 1 c	f

	REVISIONS									
REV	DESCRIPTION	DATE	APPROVED							

NOT APPROVED FOR PRODUCTION

		PAR			QTY		PTION			
			-1	ı	1					
		DRAWN BY: PERRITT			— \ Г		$D \wedge D M$	$\Lambda \Lambda \Lambda \cap$	LITN	
		CHECKED HEAT_		(<u>RB</u>	1 [2	くヒリ	RAKIN	MAL	$\Box\Box\Box$	
		TREAT FINISH SPEC		TITLE						
[USED ON MODEL	UNLESS OTHERWISE SPECIFIE DIMENSIONS ARE IN INCHES	D							
	?	TOLERANCES ON: DECIMALS .XXX ± .005 EDACTIONS + 1						-		
ł		XX ± .005 FRACTIONS ± 1 .XX ± .01 ANGLES ±.6		DWG 1	NO.		PART	#		REV.
f		UNLESS OTHERWISE SPECIFIED 1. BREAK ALL SHARP EDGES)				1 1 11 \ 1	11		
		.015 x 45° PR .015 R 2. DIMENSIONAL LIMITS APPLY AFTER PLATING	3	SCALE		NTS	DATE 1-28-0	06 ^{sheet} :	l of	1